§ 250.108

- (b) You must immediately control, remove, or otherwise correct any hazardous oil and gas accumulation or other health, safety, or fire hazard.
- (c) You must use the best available and safest technology (BAST) whenever practical on all exploration, development, and production operations. In general, we consider your compliance with MMS regulations to be the use of BAST.
- (d) The Director may require additional measures to ensure the use of BAST:
- (1) To avoid the failure of equipment that would have a significant effect on safety, health, or the environment;
 - (2) If it is economically feasible; and
- (3) If the benefits outweigh the costs. [64 FR 72775, Dec. 28, 1999, as amended at 73 FR 20171, Apr. 15, 2008]

§ 250.108 What requirements must I follow for cranes and other material-handling equipment?

- (a) All cranes installed on fixed platforms must be operated in accordance with American Petroleum Institute's Recommended Practice for Operation and Maintenance of Offshore Cranes (API RP 2D), incorporated by reference as specified in 30 CFR 250.198.
- (b) All cranes installed on fixed platforms must be equipped with a functional anti-two block device.
- (c) If a fixed platform is installed after March 17, 2003, all cranes on the platform must meet the requirements of American Petroleum Institute Specification for Offshore Pedestal Mounted Cranes (API Spec 2C), incorporated by reference as specified in 30 CFR 250.198.
- (d) All cranes manufactured after March 17, 2003, and installed on a fixed platform, must meet the requirements of API Spec 2C, incorporated by reference as specified in 30 CFR 250.198.
- (e) You must maintain records specific to a crane or the operation of a crane installed on an OCS fixed platform, as follows:
- (1) Retain all design and construction records, including installation records for any anti-two block safety devices, for the life of the crane. The records must be kept at the OCS fixed platform.
- (2) Retain all inspection, testing, and maintenance records of cranes for at

least 4 years. The records must be kept at the OCS fixed platform.

- (3) Retain the qualification records of the crane operator and all rigger personnel for at least 4 years. The records must be kept at the OCS fixed platform.
- (f) You must operate and maintain all other material-handling equipment in a manner that ensures safe operations and prevents pollution.

[68 FR 7426, Feb. 14, 2003, as amended at 72 FR 12092, Mar. 15, 2007; 74 FR 46907, Sept. 14, 2009]

§ 250.109 What documents must I prepare and maintain related to welding?

- (a) You must submit a Welding Plan to the District Manager before you begin drilling or production activities on a lease. You may not begin welding until the District Manager has approved your plan.
- (b) You must keep the following at the site where welding occurs:
- (1) A copy of the plan and its approval letter; and
- (2) Drawings showing the designated safe-welding areas.

§ 250.110 What must I include in my welding plan?

You must include all of the following in the Welding Plan that you prepare under §250.109:

- (a) Standards or requirements for welders;
- (b) How you will ensure that only qualified personnel weld;
- (c) Practices and procedures for safe welding that address:
 - (1) Welding in designated safe areas;
- (2) Welding in undesignated areas, including wellbay;
 - (3) Fire watches:
- (4) Maintenance of welding equipment; and
- (5) Plans showing all designated safewelding areas.
- (d) How you will prevent spark-producing activities (*i.e.*, grinding, abrasive blasting/cutting and arc-welding) in hazardous locations.

§ 250.111 Who oversees operations under my welding plan?

A welding supervisor or a designated person in charge must be thoroughly